



ALL MEMBER SCREW SPACING



Fastener Location at Wall - PBA

DRAWING NO.

TD2